

Oil Field Environmental Incident Summary

Incident: 20150731203244 **Date/Time of Notice:** 07/31/2015 20:32

Responsible Party: SM ENERGY COMPANY

Well Operator: SM ENERGY COMPANY

Well Name: J. OLSON 22-15-162-98H 2DM

Field Name: BLOOMING PRAIRIE

Well File #: 24999

Date Incident: 7/31/2015 **Time Incident:** 09:00

Facility ID Number:

County: DIVIDE

Twp: 162

Rng: 98

Sec: 22

Qtr:

Location Description:

Submitted By: Lester Ronholdt

Received By:

Contact Person: Lester Ronholdt
PO BOX 7168
BILLINGS, MT 59103-7168

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 2 Mile

Distance Nearest Water Well: 2 Mile

Type of Incident: Stuffing Box Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1.5	Gallons	1.5	Gallons		
Brine	3	Barrels	2.9	Barrels		

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

20 feet radius

Potential Environmental Impacts:

None

Action Taken or Planned:

Shut down unit. Closed ratigans. Called vac truck to suck up all spilled fluids.All recovered but a 2 to 3 gallons that had soaked in

Wastes Disposal Location: Recycle tank on location. Soil remediated in place.

Agencies Involved:

Updates

Date: 8/3/2015 **Status:** Reviewed - Assigned to Other Agency **Author:** Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a stuffing box leak, remained on location according to the report. NDIC retains oversight.